

## FIELD INSPECTION

Project Name:   Mountain Valley Pipeline   Inspector:   Matthew Grant			
Spread: Franklin County MP 266 St#14059-14060  Spread I  Weather (Wet/Dry/Rain):  Wet  STAGE OF CONSTRUCTION: (Check all that apply)  Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation  Backfilling and Grade Restoration Final Grading & Stabilization  Other:  Yes No N/A  Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?  Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
County MP 266 St#14059-14060  STAGE OF CONSTRUCTION: (Check all that apply)  Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation  Backfilling and Grade Restoration Final Grading & Stabilization  Other:  Yes No N/A  Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?  Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
Clearing			
Backfilling and Grade Restoration Final Grading & Stabilization Other:  Yes No N/A  Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?  Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?  Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	tion		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?  Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
2 condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
3 Areas of offsite sediment deposition were observed? □ ☑ □			
Comments:			
■ Area 1 –MP266 St#14059-11406 ECD in place.			

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: \_\_\_ Date: 11-5-18



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date:Tuesday, October 9, 2018





Fig. 3
Below St#14059 at 2 tone area rock conveyance has been installed.

